


ALL WIRES GO IN BOTTOM OF CONTROL BOX

- 1 - INCOMING POWER - 10-4 WIRE (65" STRIP 14-5).
- 2 - MOTOR - 10-4 WIRE (65" STRIP 8-5).
- 3 - CLUTCH 16-2 WIRE (65" STRIP 14-3), TEMP. WIRE, PILOT WIRES.
- 4 - BETA PUMP 16-2 WIRE (65" STRIP 12-3).
- 5 - BURNER SOLENOID 16-4 WIRE (65" STRIP 20-5).
- 6 - PLUG - NOT USED.
- 7 - FLOW AND PRESSURE SWITCH WIRES



| REV | DATE | BY | DESCRIPTION |
|-----|------|----|-------------|
| | | | |
| | | | |

| | | | |
|-------------------------------------|--|-----------------------|--|
| TITLE | | WIRING DIAGRAM | |
| | | 460V 3PH | |
| MODEL: | | | |
| P500 NG GC SS/BL PNL-TC CAT LIGHTS | | | |
| 440V 3PH 7.5HP E.IGN CLUTCH JIC/JET | | | |
| DRAWN BY: | | DATE: | |
| FH MT | | 12-8-2016 | |
| PART NUMBER: | | | |
| FPFEM17-1006-0 | | | |